

15-3-05
12.3.8 v. 9

SEP7 2004

Work Task: 24507 - 1

Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals



AGC2E000712

Description: Monthly AST (Above-ground Storage Tank) Visual Inspection

Visually inspect the outside of the container for (From SPCC Requirement [40 CFR 112.8(c)(6)]):

1. Signs of deterioration
2. Signs of Discharges
3. Signs of Accumulation of oil inside diked areas

Record finding in Work Order Close Out Comments.

Inspect all vessels on the attached list.

Work Type: 4. Environmental

Work order: 24507 Monthly AST (Above-ground Storage Tank) Visual Inspection

USEPA SF



1263437

Entity to Work On

Number: 710

Name: Common Plant Services

Personnel

Planner: MacVeigh Craig

Supervisor: Parker Sid

Shutdown Information

Shut entity down while work is in progress? No

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

Other Entities to Shut Down

Number

Name

Time Frame for Completing the Work

Priority: 3 Routine

Start no earlier than: 2004/08/31 12:53:55.00

Finish no later than: 2004/09/21 12:53:55.00

Shutdown period:

Estimated duration:

Planned duration: 4.00 hours

Job Premiums

Job type:

Shift:

Backlog Information:

Probability of Satisfaction: High

Material availability: Material not required

Estimated material availability date:

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

AGC2E000714

Failure Information

Generate failure analysis information: No
 Reason for failure: Closed
 Root cause: Lubrication
 Action taken: Closed
 Equipment failed due to:
 Entity:
 Catalog item:

Requirements

Part/Service	Quantity	Item Number	Probability of Satisfaction	Availability	Estimated Material Availability Date	Storeroom
--------------	----------	-------------	-----------------------------	--------------	--------------------------------------	-----------

Trade	Quantity	Time Required
PM Lube Spec	1.00	4.00 hours

Safety Instructions for this Work

Activities

Seattle Plant

Printed by: Austell Carey
 Printed on: 5/3/2005

Work Task: Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

Activity Number	Activity	Record Statistics	Record Downtime	Component Movement	Calibration Instrument Used	Comments
<input type="checkbox"/>						
Processed:	Processed on:		Done by:			

AGC2E000715

Seattle Plant

Printed by: Austell Carey
Printed on: 5/3/2005